

August 28, 2020

**IAI America Inc.**

Sales Support Dept., Sales Division

## **Notice of connector cover change of motor/encoder cable**

Thank you for your continued support of IAI Corporation.  
We will change a connector cover to prevent damage to connector by improving the flexibility of connector base.  
Please be advised of the following. We truly appreciate your understanding.

Best Regards

### Details

#### **1. Applicable Cables**

The change will be applied to the following motor/encoder cables for RCP5/RCP6 connection.

CB-CAN-MPA□□□

CB-CAN-MPA□□□-RB

CB-ADPC-MPA□□□


CB-ADPC-MPA□□□-RB

CB-PCS2-MPA□□□

CB-CA-AJ002

#### **2. Change Details**

- The connector base will be changed to bellows shape.
- The external view of the cable will be changed as shown below.



Photograph of external view

#### **3. Connection**

The connection between actuator and controller is fully compatible.

#### **4. Switching Timing**

The change will sequentially be applied from September.

- \* The switching timing will be different depending on the cable type or cable length.

End.